

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
CRAFTSMAN		

FIG. 1




FIG.2




FIG. 3




FIG.4





FIG.5

501 JOB NAME	502 OUTPUT CONDITION
503 JOB 1	OUTPUT IN PROGRESS
504 JOB 2	READY TO OUTPUT
505 JOB 3	DATA RECEPTION IN PROGRESS

FIG.6



252180-99560689  
APPROVED BY DRAFTSMAN  
O.G. FIG. CLASS SUBCLASS

FIG. 7





FIG.8



O.G. FIG.	
BY	CLASS
DRAFTSMAN	

Z62780-33160058

FIG.9





FIG.10


DIRECTORY
⋮
CODE OF DETERMINATION STEP
CODE OF INFORMING STEP
CODE OF TURNING OFF POWER SUPPLY
⋮



262180-99660680




FIG. 11



RECOVERED BY DRAFTSMAN  
 O.G. FIG.  
 CLASS SUBCLASS

FIG.12



BY CRAFTSMAN	O.G. FIG.	
	CLASS	SUBCLASS



FIG.14





FIG. 14

BY CLASS SUBCLASS

DRAFTSMAN

FIG.15




APPROVED BY	O.G. FIG.	
	CLASS	SUBCLASS
DRAFTSMAN		

462780-99660680

FIG.16

DIRECTORY
⋮
CODE OF DETERMINATION STEP
CODE OF INFORMING STEP

FIG. 17







APPROVED	O.G. FIG.	
	CLASS	SUBCLASS
BY	CRAFTSMAN	

FIG.19






FIG.20



APPROVED BY	O.G. FIG.	
	CLASS	SUBCLASS
CRAFTSMAN		

FIG.21



0.G. FIG.  
CLASS SUBCLASS  
BY  
DRAFTSMAN

FIG.22

DIRECTORY
⋮
CODE OF STORAGE STEP
CODE OF DETERMINATION STEP
CODE OF DISCRIMINATION STEP
CODE OF INFORMING STEP

FIG.23

5A01 ~	POWER OFF	90 %	5B01
5A02 ~	CHANGE IN PAPER SIZE	70 %	5B02
5A03 ~	CHANGE IN REMAINING PAPER QUANTITY	50 %	5B03
5A04 ~	GENERATION OF WARNING	25 %	5B04
5A05 ~	RESERVED	10 %	5B05
5A06 ~	RESERVED	0 %	5B06
5A07 ~	RESERVED	RESERVED	5B07
5A08 ~	RESERVED	RESERVED	5B08

APPROVED	0.G.FIG.	CLASS	SUBCLASS
BY			
CRAFTSMAN			

202780-99660680